

Bilder



Filnavn: IMG_3804.jpg

Kommentar:
Til VK1 og SK1

Lastet opp av: Thorleif Stendal
07.12.2021 10:43
Tatt: 19.05.2021 14:38



Filnavn: IMG_3803.jpg

Kommentar:
SK1

Lastet opp av: Thorleif Stendal
07.12.2021 10:43
Tatt: 19.05.2021 14:37



Filnavn: IMG_3801.jpg

Kommentar:
Mellom SK1 og SK2

Lastet opp av: Thorleif Stendal
07.12.2021 10:43
Tatt: 19.05.2021 14:20



Filnavn: IMG_3744.jpg

Kommentar:
Fra SK1 mot SK2

Lastet opp av: Thorleif Stendal
07.12.2021 10:42
Tatt: 11.05.2021 11:36



Filnavn: 58257F90-2EE8-4A42-9311-9CDBC3943E84.jpeg

Kommentar:
VK1 og SK1

Lastet opp av: Kennet Meland Bjørge
13.08.2021 08:57



Filnavn: 11DE5857-6133-4F99-9DD0-44108279F769.jpeg

Kommentar:
Fra SK1 mot eksisterende

Lastet opp av: Kennet Meland Bjørge
13.08.2021 08:57



Filnavn: D3F94D1A-CE3E-4C5D-95AE-9A92BB3E1402.jpeg

Lastet opp av: Kennet Meland Bjørge
13.08.2021 08:57



Filnavn: 2B2FB1B0-C7E8-4386-8DD7-EA98C735AE9F.jpeg

Lastet opp av: Kennet Meland Bjørge
13.08.2021 08:57



Filnavn: A1558B50-87AC-4AED-8314-BFE4DE0D81AE.jpeg

Lastet opp av: Kennet Meland Bjørge
13.08.2021 08:57



Filnavn: 77F9872A-BAEC-45C8-99DE-C2D2823DDE32.jpeg

Lastet opp av: Kennet Meland Bjørge
13.08.2021 08:57



Filnavn: 25788B62-FEAD-4E65-899D-A91B4E19FFC7.jpeg

Kommentar:
Sammenkobling fra VK1 mot eksisterende med PVC rør

Lastet opp av: Kennet Meland Bjørge
13.08.2021 08:57



Filnavn: 2019BCCE-FEBF-47A7-961A-9CD45C62313C.jpeg

Kommentar:
Sammenkobling fra VK1 mot eksisterende med PVC rør


Lastet opp av: Kennet Meland Bjørge
13.08.2021 08:57



Filnavn: 87CC77DF-AB5B-4E76-A5F1-D1D74E40A26F.jpeg

Kommentar:
Fra VK2 mot SF1

Lastet opp av: Thorleif Stendal
12.05.2021 11:21



Filnavn: 13CE672C-A314-4E61-8A73-E8E4E2E67B0D.jpeg

Kommentar:
VK2 og SK3

Lastet opp av: Thorleif Stendal
12.05.2021 11:21



Filnavn: FD5BB913-8C59-4640-9BE5-345F8DB8D89C.jpeg

Kommentar:
VK2 og SK3

Lastet opp av: Thorleif Stendal
12.05.2021 11:21