

# Hybrid Report

Blom Fiskeoppdrett AS

Kjeppevikholmen

Report period

06 Jun 2021 - 11 Jun 2021

Jun21

Highcharts.com

## Summary



**84%**Running on battery



16% Running on generator **(!** 

0h

System down time

The figures below show fuel consumption and CO2 emissions arising from power production. Reductions are calculated by comparing installed hybrid solution to a non-hybrid solution.



55% Reduced fuel 田

820 L

Diesel fuel saved in period

剧

671 L

Diesel fuel used in period



**55**%

Reduced CO2 emissions



2181 kg

Reduced CO2 emissions




1785 kg


CO2 emissions

## Consumption





The chart below shows produced power and diesel usage on a month by month basis.



### Reductions



	Savings	820 L	2181 kg
	With Battery	671 L	1785 kg
	Without Battery	1491 L	3966 kg
	Scenatio	Diesel usage	CO2 emission

Without Battery

144 h

Generator hours total

24

Generator hours per day

With Battery

24 h

Generator hours total

3.9

Generator hours per day

The chart below shows diesel usage with battery offloading versus constantly running generators at sub-optimal load.



## Operating time



Operating	Hours period	Hours per day	Share
Generator	24	3.9	16%
Battery	120	20.1	84%
Down-time	0	0	0%
Total	144	24	100%

Generator

28

Number of cycles (start/stop)

4.7

Number of cycles per day

0.8 h

Average running time per cycle

Battery

28

Number of cycles (charge/discharge)


4.7

Number of cycles per day

4.3 h

Average running time per cycle

The chart below shows daily running hours for both generators and battery. Fjord Hybrid considerably reduces time spent running on generators.



## Service

#### ✓ Completed services

2021-06-09 00:00:00	Device Status Summary	Genset1 Resolved Satte grense veridene	Description Comments til 46 og 54 Hz	ErrorDiscovery	Billable Hours Non-Billable Hours	0.5
2021-06-07 22:45:00	Device Status Summary	Hybrid Description ErrorDiscovery Billable Hours 1 Resolved Comments Non-Billable Hours Vurdere å justere grensenivåene på OnLoadFault, eventuelt utbedre Genset, slik at den leverer mer stabil spenning. 08.06.2021 Nok en tilsvarende hendelse 09.06.2021 - Sak avsluttes se ID1262				

Scheduled maintenance

**E** Comments