

137-VEG

-00 FF
-01 OOOOOOOOOOOO DDDDDDDDDDD VVVVVVVVVVVV KKKKKKKKKKKK OOOOOOOOOOOO
-02 SSSSSSSSSS KKKKKKKK NNNNNNNN TTTTTTTT TTTTTTTT II.III Bk MMMMMMM
-03 TTTTTTTTTT KKKKKKKK HHH.HHHH VVV.VVVV AAAA.AAA SS.SSS Bk MMMMMMM
-04 TTTTTTTTTT KKKKKKKK HHH.HHHH DDDD.DDD AAAA.AAA SS.SSS Bk MMMMMMM
-05 PPPPPPPPPP KKKKKKKK XXXXXXXX.XXX YYYYYYY.YYY ZZZZ.ZZZ Bk MMMMMMM
-06 PPPPPPPPPP KKKKKKKK PPPPPPPP.PPP AAAAAA.AAA ZZZZ.ZZZ Bk MMMMMMM
-07 PPPPPPPPPP KKKKKKKK dXXXXXX.XXX dYYYYYY.YYY dZZZ.ZZZ Bk MMMMMMM
-08 Epi E1 E2 E3 E4
-09_Pi Sammenheng FF MMMMMMM

Innmåling for overtaking frå Gnr 137 bnr 608 til kommunal veg

-00 Leica Geosystems AG
-00 Instrument: CS15 Måledato: 27.05.2014
-00 Målejobb: 137-VEG Operatør: ER
-00 Jobbeskrivelse:

| | | | | |
|---------------|-------------|------------|--------|-------|
| 05 M-Ref 0041 | 6718218.805 | 296622.928 | 65.488 | 0.000 |
| 05 01 | 6719368.497 | 295091.623 | 55.531 | 0.012 |
| 05 02 | 6719369.493 | 295097.360 | 55.514 | 0.011 |
| 05 03 | 6719366.295 | 295100.036 | 55.408 | 0.009 |
| 05 04 | 6719363.649 | 295102.568 | 55.322 | 0.011 |
| 05 05 | 6719360.202 | 295105.374 | 55.248 | 0.009 |
| 05 06 | 6719357.344 | 295107.280 | 55.054 | 0.010 |
| 05 07 | 6719354.359 | 295109.072 | 54.853 | 0.008 |
| 05 08 | 6719352.525 | 295111.306 | 54.711 | 0.010 |
| 05 09 | 6719350.944 | 295113.716 | 54.559 | 0.010 |
| 05 10 | 6719349.450 | 295115.536 | 54.386 | 0.009 |
| 05 11 | 6719347.736 | 295117.003 | 54.191 | 0.010 |
| 05 12 | 6719342.227 | 295117.829 | 53.718 | 0.010 |
| 05 13 | 6719337.763 | 295120.754 | 53.330 | 0.013 |
| 05 14 | 6719330.948 | 295124.934 | 52.836 | 0.009 |
| 05 15 | 6719268.443 | 295149.143 | 46.925 | 0.014 |
| 05 16 | 6719264.021 | 295153.078 | 46.689 | 0.010 |
| 05 17 | 6719250.732 | 295161.827 | 45.258 | 0.010 |
| 05 18 | 6719233.576 | 295169.706 | 43.686 | 0.010 |
| 05 19 | 6719232.259 | 295174.179 | 43.465 | 0.015 |
| 05 20 | 6719233.752 | 295179.874 | 43.582 | 0.015 |
| 05 21 | 6719246.088 | 295211.220 | 44.255 | 0.017 |
| 05 22 | 6719251.459 | 295221.918 | 44.809 | 0.009 |
| 05 23 | 6719256.076 | 295227.360 | 45.442 | 0.011 |
| 05 24 | 6719262.488 | 295231.406 | 46.038 | 0.015 |
| 05 25 | 6719269.644 | 295233.210 | 46.779 | 0.009 |
| 05 26 | 6719276.875 | 295232.317 | 47.512 | 0.009 |
| 05 27 | 6719283.501 | 295229.446 | 48.280 | 0.012 |
| 05 28 | 6719288.638 | 295225.119 | 49.000 | 0.008 |
| 05 29 | 6719292.086 | 295219.606 | 49.761 | 0.009 |
| 05 30 | 6719294.581 | 295213.499 | 50.245 | 0.009 |
| 05 31 | 6719299.850 | 295205.181 | 50.754 | 0.013 |
| 05 32 | 6719306.568 | 295200.277 | 50.926 | 0.008 |
| 05 33 | 6719310.132 | 295198.097 | 51.024 | 0.010 |
| 05 34 | 6719320.772 | 295193.438 | 51.254 | 0.011 |
| 05 35 | 6719326.561 | 295189.135 | 51.484 | 0.017 |

Knarvik 27.05.2014



Lindås Kommune Geodata avd

Einar Rydland

Lindås kommune