



### SITUASJONSPLAN

GNR.123 BNR.146 , RISASJØEN, LINDÅS KOMMUNE

OK GULV: KOTE +25,7

FOR TERRENGSNITT A-A OG B-B SE TEGNING 20714103A11.

B	FELLES AVKJØRSEL MED GBNR. 123/145	18.08.16/LAH
A	SVINGRRADIUS 4m AVKJØRSEL	12.08.16/LAH
REV.	DESCRIPTION	DATE/SIGN
	<p><b>NOTE!</b></p> <ul style="list-style-type: none"> <li>* PART OF DRAWING MAY NOT BE SHOWN IN SCALE</li> <li>* DO NOT TAKE MEASURES ON DRAWING</li> <li>* ONLY RELAY ON GIVE DIMENSIONS</li> </ul>	<p>ACCORDING TO INTERNATIONAL LAWS, THIS DRAWING IS THE PROPERTY OF ARKOCONSULT AS. THE DRAWING CAN NOT BE USED, MADE PUBLIC OR HANDED OVER TO A THIRD PART WITHOUT OUR WRITTEN CONSENT. ANY INFRINGEMENT WILL LEAD TO LEGAL PROCEEDINGS.</p>
<p>BOLIG &amp; EIENDOM AS RISASJØEN, 123/146</p>		<p>REVISION/DATE: <b>B/18.08.16</b></p>
<p>SITUASJONSPLAN</p>		<p>PROJECT NO.: 2014103</p>
<p><b>arkoconsult</b> ARKOCONSULT AS, Postboks 103, 5291 Vålestrf. Tel.: 56390003 – Fax.: 56191130 – Mob.: 93241511 Mail: post@arkoconsult.no – Org.nr.: 997089782 MVA</p>		<p>DRAWING NO.: 20714103A10</p>
SCALE:	1:500	FORMAT: A3
DRAWN:	LAH	DATE: 22.04.2014
CHECKED:	PKT	DATE: 12.02.16