

```

-00 FFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFF
-01 OOOOOOOOOO DDDDDDDDDDD VVVVVVVVVVVV KKKKKKKKKKKK OOOOOOOOOO
-02 SSSSSSSSSS KKKKKKKK NNNNNNNN TTTTTTTT TTTTTTTT II.III Bk MMMMMMM
-03 TTTTTTTTTT KKKKKKKK HHH.HHHH VVV.VVVV AAAA.AAA SS.SSS Bk MMMMMMM
-04 TTTTTTTTTT KKKKKKKK HHH.HHHH DDD.DDD AAAA.AAA SS.SSS Bk MMMMMMM
-05 PPPPPPPPPP KKKKKKKK XXXXXXXX.XXX YYYYYY.YYY ZZZZ.ZZZ Bk MMMMMMM
-06 PPPPPPPPPP KKKKKKKK PPPPPPPP.PPP AAAAAA.AAA ZZZZ.ZZZ Bk MMMMMMM
-07 PPPPPPPPPP KKKKKKKK dXXXXXX.XXX dYYYYY.YYY dZZZ.ZZZ Bk MMMMMMM
-08 Epi E1 E2 E3 E4
00 -09_Pi Sammenheng FFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFF MMMMMMM
-00 Leica Geosystems AG
-00 Instrument: GX1230 GG Måledato: 23.12.2016
-00 Målejobb: 1-169ASB Operatør:km
-00 Jobbeskrivelse: Innmålt bygg
05 1 8250 6716610.536 294553.561 5.129 0.015
05 2 8250 6716610.162 294554.784 5.127 0.011
09_91
05 3 5006 6716604.026 294557.622 7.802 0.012
05 4 5006 6716612.706 294563.664 7.794 0.011
05 5 5006 6716604.240 294575.805 7.972 0.011
05 6 5006 6716595.561 294569.753 7.997 0.017
05 3 5006 6716604.026 294557.622 7.802 0.012
09_99
05 HPKT1 1000 6716595.874 294571.474 7.420 0.015
09_91
05 10 6002 6716595.368 294569.784 7.427 0.011
05 11 6002 6716594.097 294568.910 7.475 0.014
05 12 6002 6716597.874 294563.458 7.680 0.011
05 13 6002 6716599.165 294564.351 7.650 0.012
09_99
05 GR1K 4051 6716604.469 294588.813 7.518 0.013

```