



| Id | Øst        | Nord        |
|----|------------|-------------|
| 1  | 282559,453 | 6728939,734 |
| 2  | 282564,810 | 6728947,514 |
| 3  | 282575,549 | 6728940,113 |
| 4  | 282569,858 | 6728931,849 |
| 5  | 282566,397 | 6728934,232 |
| 6  | 282565,742 | 6728933,281 |
| 7  | 282564,845 | 6728933,114 |
| 8  | 282562,085 | 6728935,014 |
| 9  | 282561,925 | 6728935,920 |
| 10 | 282562,919 | 6728937,364 |
| 11 | 282570,494 | 6728953,182 |
| 12 | 282574,031 | 6728958,345 |
| 13 | 282580,753 | 6728953,761 |
| 14 | 282577,186 | 6728948,582 |

|  |                |            |     |           |       |  |
|--|----------------|------------|-----|-----------|-------|--|
| Dato   | Konstr./tegnet | Godkjent   | KKL | Målestokk | 1:200 | <br>Erstatning for: Erstattet av: |
| Situasjonsplan<br>Gnr. 45 Bnr. 465<br>Selfallet 123, 5936 Manger |                |            |     |           | 901   |  |
| Henvising:   |                | Beregning: |     |           |       |  |