

185-298INNM1710

-00 FFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFF  
-01 000000000000 DDDDDDDDDDD VVVVVVVVVVVV KKKKKKKKKKKK 000000000000  
-02 SSSSSSSSSS KKKKKKKK NNNNNNNN TTTTTTTT TTTTTTTT II.III Bk MMMMMMM  
-03 TTTTTTTTTT KKKKKKKK HHH.HHHH VVV.VVVV AAAA.AAA SS.SSS Bk MMMMMMM  
-04 TTTTTTTTTT KKKKKKKK HHH.HHHH DDDD.DDD AAAA.AAA SS.SSS Bk MMMMMMM  
-05 PPPPPPPPPP KKKKKKKK XXXXXXXX.XXX YYYYYYY.YYY ZZZZ.ZZZ Bk MMMMMMM  
-06 PPPPPPPPPP KKKKKKKK PPPPPPPP.PPP AAAAAA.AAA ZZZZ.ZZZ Bk MMMMMMM  
-07 PPPPPPPPPP KKKKKKKK dXXXXXXX.XXX dYYYYYY.YYY dZZZ.ZZZ Bk MMMMMMM  
-08 Epi E1 E2 E3 E4  
-09\_Pi Sammenheng FFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFF MMMMMMM

-00 Leica Geosystems AG

-00 Instrument: CS15 Måledato: 17.10.2018


-00 Målejobb: 185-298INNM 1710 Operatør: ER

-00 Jobbeskrivelse:

|       |             |            |        |       |
|-------|-------------|------------|--------|-------|
| 05 01 | 6718983.469 | 295729.143 | 55.774 | 0.015 |
| 05 02 | 6718978.421 | 295734.483 | 55.792 | 0.019 |
| 05 03 | 6718977.676 | 295733.834 | 55.774 | 0.014 |
| 05 04 | 6718973.173 | 295738.576 | 55.780 | 0.011 |
| 05 05 | 6718966.162 | 295731.953 | 55.791 | 0.012 |
| 05 06 | 6718969.337 | 295728.611 | 55.775 | 0.011 |
| 05 07 | 6718969.763 | 295729.018 | 55.784 | 0.014 |
| 05 08 | 6718971.787 | 295726.882 | 55.793 | 0.014 |
| 05 09 | 6718972.238 | 295727.282 | 55.783 | 0.010 |
| 05 10 | 6718976.597 | 295722.667 | 55.799 | 0.010 |

Knarvik 17.10.2018

Lindås kommune Geodata avd.

  
Einar Rydland

**Lindås kommune**