



N:\10208216-01\10208216-01-03 ARBEIDSDOKRÅD\10208216-01\10208216-01-04 TEGNINGER\lay_1021-va_grofter_kumskisser.dwg - Layout: (G401)

| | | | | | |
|--|---------------------------|--|-----------------------|-------------------|--|
| Rev | Beskrivelse | Dato | Tagg | Kontr. | Godkj. |
| | Consto AS RNH Helsehus | | VA | | A1/A3 |
| | Kumskisse spillvann | | | | Dato: 05.11.2018 Format/Helsestokk: 1:10 (A1) 1:20 (A3) |
| Multiconsult www.multiconsult.no | | Status VA0 - Rammeplan Oppdragsnr.: 10208216 | Konstr./Tegnet KS0 | Kontrollert GS | Godkjent OAL |
| | | | | Tegningsnr.: G401 | Rev: 01 |