

**Servicedatoer for avløpsreanlegg:**

B = Bestilt anlegg - L = Levert anlegg - M = Montert anlegg - S = Service

T = Slamtomming - F = Feilsøking - E = Ekstra besøk - K = 1 kanne kjemikalie

 Ruter: [Slamtomming](#) [Avvik](#)
**LINDÅS 10**

Type	Navn	Kundnr.:	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018
BAI	Andreas Kolås Kolåsvegen 163 5955 Lindås	2072											L; 18/10	M; 4/7	S,K;27/6 S,K;3/12 E;16/12	E;17/1 S,K;24/6 T; 1/9 S,K;27/11	S,K;4/6 T; 29/7	S,K;8/1 S, K; 28/7 S,K; 29/11	S,K; 22/5 S,K;24/11	S,K; 29/6 S,K; 17/12
BB1	Alfhild Skårnes Skårnesvegen 172 5955 Lindås	1903										M; 6/7 S,K;2/11	S,K;27/4 S;20/12	S,K;20/6	S;14/1 S;27/6 S;3/12	S;24/6 S;27/11	S;4/6	S,K;8/1 S, K; 28/7 S; 29/11	S; 22/5 S;24/11 E;15/12	S,K; 29/6 S,K; 17/12
BAI	Biørø Anne Saltnes Veråsvegen 332 5955 Lindås	1669			2003	E: 10.03.				T: 14/5 S: 3/10	S,K; 13/3 T: 1/4 S: 12/9	S,K; 15/1 T,E: 16/4 S: 25/6 E: 16/7	S;7/4 S,K;2/11	S,K;27/4 S,K;20/12	S;20/6	S,K;14/1 E;13/2 S;27/6 S;3/12	S,K;24/6 S;27/11	S;4/6 T; 1/9	S,K;8/1 S: 28/7 S: 29/11	S; 22/5 S;24/11 S: 29/6
BAI	Idunn Eide Fjellangervegen 5956 Vågeeidet	1949										B; 29/4 L; 8/5 M; 5/6	S,K;7/4 S;2/22	S;27/4 S;20/12	S;20/6	S,K;14/1 S;27/6 S;3/12	E;17/1 S;24/6 S;27/11	S;4/6	S;8/1 S, K; 28/7 S: 29/11	S; 22/5 S;24/11 S: 17/12
BAI	Kurt Fjellanger Fjellangervegen 63 5956 Vågeeidet	1823								L: 9/5 M: 9/7	S: 13/3 S: 12/9	S: 15/1 S,K; 25/6	S,K;7/4 S;2/11	S;9/5 S;20/12	S,K;20/6	S;14/1 S;27/6 S,K;3/12	S;24/6 S,K;27/11	S;4/6 T; 29/7	S;8/1 S: 28/7 S: 29/11	S; 22/5 S;24/11 S,K; 29/6 S: 17/12
BD1	Bent Arne Rognaldsen Øvre Skodvin 5956 Hundvin	2197													L; 21/10 M; 7/11	S;19/6 S,K;27/11	S;4/6	S,K;8/1 S, K; 28/7 S: 29/11	E;6/2 S,K; 22/5 T; 7/9 S,K;24/11	S; 29/6 S,2K; 17/12