

Servicedatoer for avløpsrenseanlegg:
B = Bestilt anlegg - L = Levert anlegg - M = Montert anlegg - S = Service
T = Slamtomming - F = Feilsøking - E = Ekstra besøk - K = 1 kanne kjemikalie

Ruter: Slamtomming: Avvik:

LINDÅS 1

Type	Navn	Kundenr.:	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019
BA1	Lars-Emil Vabø Liteåsvegen 65 5955 Lindås	1640			2003				T: 14/5 S: 3/10	S,K: 13/3 S,K: 12/9 T: 22/9	S,K: 15/1 S,K: 25/6	M:23/3 S,K:2/11 E:14/12	E:11/3 S,K:27/4 S:20/12	E,S:7/6	S:16/1 S:1/7 S:10/12	S,K:24/6 S:20/11	S:5/6 S:30/12	S: 27/7 S: 5/12	S:24/5	S: 10/1 S,K: 13/7	
BA1	Gunhild Hone Litlåsvegen 67 5955 Lindås hus ikke bebodd, datter	1587	Levert: 20.6. Montert: 16.7.	S: 22/8 S: 19/11					T: 9/5 S: 3/10	S: 13/3 E: 28/3 K: 1/8 S: 12/9 T: 22/9	S: 15/1 S: 25/6	S: 7/4 S,K:2/11	S,K:27/4 S,K:20/12	S,K,T:18/6	S:16/1 S:1/7 S:10/12	S:24/6 S:20/11	S:5/6 S,K:30/12	S: 27/7 S, K: 5/12	S:24/5 T: 7/9	S: 10/1 S: 13/7	
BA1	Bjørn Øyvind Færestad Liteåsvegen 67 5955 Lindås	1664			Levert: 02.07.	2004		E: 19/1	T: 14/5 S: 3/10	S: 13/3 S: 12/9 T: 14/11	S,K: 15/1 E,K: 24/4 S: 25/6 E:16/12	E,K:5/1 S:7/4 S:2/11	S,K:27/4 S,K:20/12	S,K:18/6	S:16/1 S,K:1/7 S:10/12	E:14/2 T: 20/3 S:24/6 S:20/11	E:20/1 E,K:27/1 S:5/6 S:30/12	E:4/2 E:19/2 S: 27/7 T: 25/8 S: 5/12	E: 27/1 E, K: 7/2 E:22/2 E:21/4 S:24/5	S: 10/1 S,K: 13/7	
BB1	Elin Dvrov Spjøtoyvegen 52 5955 Lindås	1875							L: 29/11	M: 30/4 S,K: 12/9	S,K: 15/1 E: 19/2 S: 25/6	T:7/4 E,K:11/5 S,K:2/11	E:8/4 S,K:27/4 S,K:20/12	S,K:18/6	S:16/1 S:1/7 S:10/12	S:24/6	S:16/6 S,K:30/12	S, K: 27/7 S, K: 5/12	S:24/5	*E: 10/1 *E: 27/4	